

Biyagama 2	N/A	N/A	At Relay Room: <ul style="list-style-type: none"> • F871 Main 1 Protection <ul style="list-style-type: none"> ○ General Trip ○ R Pickup ○ B Pickup ○ N Pickup ○ Diff. Trip ○ CR • F872 Main 2 Protection <ul style="list-style-type: none"> ○ R Pickup ○ B Pickup ○ N Pickup ○ Diff. Trip ○ Zone1/1B trip ○ Carrier Send ○ Carrier Received ○ AROPTD
Victoria 2	N/A	N/A	At Relay Room: <ul style="list-style-type: none"> • F871 Main 1 Protection <ul style="list-style-type: none"> ○ N Pickup
U2 Generator T/F	N/A	N/A	At Relay Room: <ul style="list-style-type: none"> • F67 Relay <ul style="list-style-type: none"> ○ Y Pickup ○ B Pickup ○ N Pickup

3. Restoration

Equipment	Restored time
Anuradhapura 1	11:48

4. Brief description of incident by officer in charge [OEE] at that time:

At 11:37 hrs Biyagama Line 1 tripped from Kotmale. Informed SCC and restored the line after clearing all the indication as per the instructions by SCC.

John Bumb (EEO)
15/06/2015


5. Remedial actions taken to avoid reoccurrence of such failure / (EE (C&I/ EEM)'s note):

Tripping may be due to an outside fault. No faults were detected in Kotmale machines or switchyard equipment.

[Signature]
14/06/2015

6. Remarks

This is not due to a fault at Kotmale,
supply restored after cancelling the
indicators



CHIEF ENGINEER

.....
Officer In-Charge of the Power Station
Kotmale Power Station
Ceylon Electricity Board
MAWATURA

Date: 15/06/2015

Copy: DGM (MC) - f.i. Pl.